Citation Number: 6578			Dat	e: July 13, 2017
Facility Name: Ridgewood Specialty Care		Survey I June 26	Dates: , 27, 28, 29, 2	017
Facility Address/City/State/Zip 1977 Albia Road				
	HL			
Rule or Code Natu Section	re of Violation	Class	Fine Amou	nt Correction date
or environmental hat [ARC 1398C, IAB 4/2/14, effect of the content	exprotected against physical zards to themselves. (I, II, III) fective 5/7/14] w, observations, and staff ailed to ensure the resident as free from accident hazards residents sampled (Residents y, the facility failed to implement os in side rails were not large sk for entrapment for Residents to ensure the side rails did not in the resident could become ts #3 and #7 at risk of serious leath due to entrapment within ported a census of 55 residents. and Drug Administration's fety Workgroup article, "Clinical essment and Implementation of Long Term Care Facilities, and dated April 2003, indicated, in f bed rails should be based on dical needs and should be		\$2000.00 Held In Suspension	Neceipt Page 1
	ring, for example, turning and ed and providing a hand-hold			Page 1 of <i>1</i>

Facility Administrator

Date

Citation Numb 6578	er:				Date: J	uly 13, 2017
Facility Name: Ridgewood Sp			Survey I June 26,		29, 2017	
Facility Addres	ss/City/State/Zip ad					
		HL				
Rule or Code Section	Natur	e of Violation	Class	Fine A	Amount	Correction date
	by a care planInspect upgrade equipment (bedidentify and remove pot hazards and appropriate patient needs, consider is determined that bed it to bed rail interface sho falling between the mat and monitoring of the besuch as patient/caregive ongoing" According to the FDA's Staff article, "Hospital B Assessment Guidance 3/10/06, "For 20 years, which vulnerable patien hospital beds while und health care facilities. Than event in which a patior entangled in the space mattress, or hospital be may result in deaths an received approximately period of 21 years from 2006. In these reports, injured, and 158 were in serious injury as a result entrapment events have the bed rails, between tunder bed rails, between tunder bed rails, between	bed, should be accompanied, evaluate, maintain, and ds/mattresses/bed rails) to ential fall and entrapment ely match the equipment of ing all relevant risk factorsIf it rails are requiredThe mattress uld prevent an individual from tress and bed. Maintenance ed, mattress, and accessories er assist itemsshould be Guidance for Industry and FDA and System Dimensional and to Reduce Entrapment," issued FDA has received reports in the term "entrapment" describes ent/resident is caught, trapped, the in or about the bed rail, deframe. Patient entrapments describes describes in the population of intervention. These eroccurred in openings within the bed rails, and between the pot boards. The population				

Facility Administrator Date

If, within thirty (30) days of the receipt of the citation, you (1) do not request a formal hearing or; (2) withdraw your request for formal hearing, and (3) pay the penalty; the assessed penalty will be reduced by thirty–five percent (35%) pursuant to lowa Code section 135C.43A (2013).

Page 2 of 11

Citation Numb 6578	er:				Date: Ju	uly 13, 2017
Facility Name: Ridgewood Specialty Care			Survey I June 26,		29, 2017	
Facility Address 1977 Albia Roa	ss/City/State/Zip ad					
		HL				
Rule or Code Section	Natur	e of Violation	Class	Fine A	mount	Correction date
	residents, especially the restless, or who have usen trapments have occursettings" An undated facility docuthe following guidelines. 1. All residents will be appropriateness for use on admission. 2. Ongoing use of bed change in condition, and 3. Evaluations will inclued. Risks and benefits of discussed with resident informed consent will be 5. Care Plan will addressor device. 6. Assure that the bed's for the resident's size at 7. Follow the manufact specifications for installing The MDS(Minimum Dat 6/6/17, listed diagnoses cerebrovascular accides sided paralysis). The M required supervision and limited assistance of 1 sextensive assistance of dressing, toilet use, person the control of the control	evaluated for the of bed rails prior to initiation rails will be evaluated quarterly, d with change of equipment. If the derisk of entrapment of the rail usage will be and family representative and explained prior to usage. The second is dimensions are appropriate and weight. The second in the recommendations and and maintaining bed rails. The second is a second in the recommendation of the second in the s				

Facility Administrator Date

If, within thirty (30) days of the receipt of the citation, you (1) do not request a formal hearing or; (2) withdraw your request for formal hearing, and (3) pay the penalty; the assessed penalty will be reduced by thirty–five percent (35%) pursuant to lowa Code section 135C.43A (2013).

Page 3 of 11

Citation Numb 6578	er:				Date: Ju	uly 13, 2017
Facility Name: Ridgewood Specialty Care			Survey I June 26,		29, 2017	
Facility Addres	ss/City/State/Zip ad					
		HL				
Rule or Code Section	Natur	e of Violation	Class	Fine A	mount	Correction date
	Mental Status) as 8 out impaired cognition. The 1 fall without injury sind A care plan entry, dated had 2 1/2 side rails up to bed mobility. The care falls on 3/8/17 and 3/15 and weakness. The resident's "Side Ra 3/2/17, stated the reside a. had an alteration in scognitive decline b. had a history of falls c. had difficulty with bale e. took medication that precautions f. expressed a desire to bed to promote independent lying on the bale looks. One side of the both sides of the bed. An observation on 6/25/14. An observation on 6/25/15.	safety awareness related to lance or poor trunk control would require increased safety b have the side rails up while in				
		/17 at 3:53 p.m. revealed Staff g Assistant) assisted the				

Page 4 of 11

Facility Administrator Date

Citation Numb 6578	er:				Date: J	uly 13, 2017
Facility Name: Ridgewood Specialty Care			Survey I June 26,		29, 2017	
Facility Address 1977 Albia Roa	ss/City/State/Zip ad					
		HL				
Rule or Code Section	Nature	e of Violation	Class	Fine A	Amount	Correction date
	resident out of the bed.					
	During an observation of surveyor was able to plathrough 2 vertical bars of top bar of the side rail at the resident's bed. During an observation of Resident #3's bed was overtical slats of the bed Maintenance Superviso with the surveyor approximattress would be and the surveyor approximattress and be approximattress and bed rails maintenance program to entrapment.	outside with no mattress. The measured 8 inches. The r was present and concurred ximately how high a mattress be between where the top of the the top rail measured 9 inches. The following dates: 3/15/17, 1/9/17. The form did not evaluation entailed. The following dates: 3/15/17, 1/9/				
	6/26/17, stated all reside to ensure the side rail m regulatory standards of	evement Project Plan", dated ent's beds would be assessed neasurements were within the 4 3/4 inches and the facility with more than the allotted				

Page 5 of 11

Facility Administrator Date

Citation Numb 6578	er:				Date: Ju	uly 13, 2017
Facility Name: Ridgewood Sp			Survey I June 26,		29, 2017	
Facility Addres	ss/City/State/Zip ad					
		HL				
Rule or Code Section	Natur	e of Violation	Class	Fine A	mount	Correction date
	spacing.					
	During an interview duri 1:45 p.m., the DON(Dire resident did not speak a					
	stated she thought the good be no greater than 8 incomes.	6/26/17 at 2:49 p.m., the DON gap between side rails should thes. She stated the facility did order for side rails for the				
		6/26/17 at approximately 3:30 tant stated the facility removed				
	CNA(Certified Nursing A resident scoot down in I	Ouring an interview on 6/27/17 at 10:47 a.m., Staff H CNA(Certified Nursing Assistant) stated she saw the esident scoot down in bed to the end but did not see the resident attempt to crawl over the side rails.				
		6/27/17 at 10:51 a.m., Staff G e resident sit up in bed but did to get out of bed.				
	Maintenance Superviso requirements for the be no greater than 8 inchestarted measuring the bof the year and was using the started measuring the bof the year and was using the started measuring the bof the year and was using the started measuring the bof the year and was using the started measuring the started measuring the started measuring the started measuring the started measurements and the started measuring th	d rail measurements were to be s between bars. He stated he sed rails around the beginning ang 8 inches as the guideline.				
	2. The Quarterly Minim	um Data Set (MDS- a federally				

Facility Administrator

Date

Page 6 of 11

Citation Numb 6578	er:				Date: J	uly 13, 2017
Facility Name: Ridgewood Specialty Care			Survey I June 26,		29, 2017	
Facility Addres	ss/City/State/Zip ad					
		HL				
Rule or Code Section	Nature	e of Violation	Class	Fine A	mount	Correction date
	BIMS (Brief Interview of indicated severe long ar Resident # 7 required exfor bed mobility, transfe and toilet use. The MDS incontinency of both box only understood verbal reply appropriately on a assessment documente inches and 122 pounds. Alzheimer's Disease, a Syndrome, and had expadmission to the facility. The plan of care with a 12/14/2016 directed fac with a pressure reduction to promote independence # 7 became a Hospice p 06/23/2017. The facility's Side Rail Rassessment date of 03/2 would provide safety an movement for the reside acuity and decreased he communication and underight ankle and decline in risk of falls. The plan of	date of 03/21/2017 revealed a Mental Status) of 3 which and short term memory deficits. Attensive assistance from 2 staff ars, dressing, personal hygiene, S documented complete and bladder. The resident communications and could limited basis. The ad height and weight as 4 foot 8 and Active diagnoses included seizure disorder, Downs are ienced at least 1 fall prior to an mattress and 2 half side rails are and bed mobility. Resident control of the composite of the control of the cont				

Page **7** of **11**

Facility Administrator

Date

Citation Numb	per:				Date: Ju	uly 13, 2017
Facility Name: Ridgewood Specialty Care			Survey I June 26	Dates: , 27, 28, 29	9, 2017	
Facility Addre	ss/City/State/Zip ad					
		HL				
Rule or Code Section	Natur	e of Violation	Class	Fine An	nount	Correction date
	revealed a score of 16. indicated a high risk for An observation on 06/20 Resident # 7 in bed with approximately 30 degre left side. A Hospice repi head of the bed. A tan cover the mattress on the On 06/26/2017 at 12:25 (certified Nursing Assist Resident # 7 and positions side with a body pillow but up approximately 30 de At 1:05 P.M. on 06/27/2 resident higher in bed (so rolled the bed up to the the resident's head 18 to mattress. Around 1:10 P.M., as So resident nourishment, the side of the bed by the uneyes unfocused and calculper half bed rail meas the horizontally and 1 foot 6 upper bars 4 inches apart and the 17.5 inches. A tan overlated the side of the second to the part and the 17.5 inches. A tan overlated the side of the second to the se	falls. 6/2017 at 12:10 P.M., found in the head of the bed elevated es. The resident laid on the resentative sat in a chair by the overlay air pad could be seen e bed. 6 P.M., Staff I and Staff J cants) provided cares for oned the resident on the right behind, and the head of the bed				

Facility Administrator

Date

Page 8 of 11

Citation Numb 6578	er:				Date: Ju	uly 13, 2017
Facility Name: Ridgewood Specialty Care			Survey I June 26,		29, 2017	
Facility Addres	ss/City/State/Zip ad					
		HL				
Rule or Code Section	Natur	e of Violation	Class	Fine A	Amount	Correction date
	sides extended out into Observations of the dark half way point between top of the bed to the bot frayed area brown in cowide. The raised upper center point of the bed when the head of the bed is raised, the blindown to around a half in The area where the mark when raised to the 60 dithe lowest bed rail bar to 10 inches from the endicenter of the bed) to the form a "V" shape openion A review of the medical 06/26/17 and 6/27/2017 06/26/2017 at 12:10 P.M fowler position (60 to 90 bed). The resident's wr 06/26/2017 at 1:30 P.M position. 06/27/2017 at 08:30 A.M and the head of the bed 06/27/2017 at 11:30 A.M restless. The restlessne P.M.	k blue/black mattress at the the upper and lower rail from tom displayed a worn and lor and approximately 8 inches half rail angled higher at the where the mattress bends ed is raised. When the head of ue/black mattress crushed inch in depth. It is mattress met the bend of the bed egree range left a gap under to the mattress of 7.5 inches by of the bed rail (toward the emattress angles upward to ing.				

Page **9** of **11**

Facility Administrator

Date

Citation Numb 6578	er:				Date: Ju	ıly 13, 2017
Facility Name: Ridgewood Specialty Care Facility Address/City/State/Zip			Survey D June 26,		29, 2017	
1977 Albia Roa						
		HL				
Rule or Code Section	Nature	e of Violation	Class	Fine A	mount	Correction date
	non-ambulatory, conscir falls, poor bed mobility a medications, and a diag The screen failed to ide compromised visual acu cognitive ability and safe Interventions included be pillows, wedges, and on Hospice would deliver be particular bed. (Delivered On 06/27/2017 the facility representative by phone Informed Consent and Fan agreement to utilize to Observation of Resident Hospice on 06/27/2017 and rails to fit together wentrapment issues. The facility Administrator informed of the Immediation 1:00 A.M., due to the requirement of only 4.75 Resident #7's side rail gets.	Intify the resident's uity along with a decrease in ety awareness. The positioning devices, body the way slides for beds. The positioning devices, body the way slides for beds. The position of the potential of the potential for side rails appropriate to this ed on 06/27/2017). The positioning devices, body the way slides for beds. The position of the position of the position of the potential for side rails appropriate to this ed concerning the Bed Rails are position of the position of the position of the position of the potential for side rail when the potential for				Page 10 o

1

Facility Administrator

Date

Citation Number 6578	:	Date:			ıly 13, 2017
Facility Name: Ridgewood Spec			Survey Da June 26, 2	ates: 27, 28, 29, 2017	
Facility Address 1977 Albia Road	/City/State/Zip				
		HL			
Rule or Code Section	Nature	e of Violation	Class	Fine Amount	Correction date
	Administrator		Date		Page 11 of 11